


## LanTEK III Series Software Release Note

Software Version: **3.215**

Release Date: 20 Dec 2018

Software version 3.117 or later must be installed on the LanTEK III before updating to version 3.215.

To check which version you have installed, select home screen, select Instrument then About to view the current version.



Current  
Software  
version

If the version is older than 3.117 then you must update to 3.117 before proceeding to update to 3.215. Unzip the "3\_117\_archive.zip" and follow the instruction in "3.117 installation.pdf" to install the 3.117 software.

This release note accompanies software version 3.215 of the LanTEK III Series cable certifier from TREND Networks. The following changes have been made from version 3.212:

- Improvements to prevent random partner finder beep. Note that a partner finder beep may be heard on the remote unit when the Main unit is saving results.